

IN THE DRAWINGS

In Figs. 5-11, members 6, 7, 9, 8, 7, 10 and 6, respectively, were originally shaded to indicate heating. On the attached replacement sheets of these Figs. the shading is replaced zig-zag phantom lines that may suggest heating by zig-zag resemblance to electrical resistance but do not introduce such electrical resistance because in phantom lines.


In Figs. 9-11, more familiar liquid-indicating shading is used for ink 14.














4/5



F1G.9

FIG. 10






P-PLACEMENT SITEE / 10/018,302 U 013688-5

5/5





F1G. 1